

Goodyear Canada Inc.

450 KIPLING AVENUE, TORONTO, ONTARIO, M8Z 5E1

April 29, 2026

IMPORTANT SAFETY RECALL **Transport Canada Recall No. 2026-198**

Goodyear Eagle F1 SuperSport Tire Recall Size 255/35ZR20

Dear Goodyear Eagle F1 SuperSport Customer:

This notice is sent to you in accordance with the *Motor Vehicle Safety Act*. This is to inform you that your tire may contain a defect that could affect the safety of a person. Goodyear Canada Inc. (Goodyear) has determined that a certain quantity of Goodyear Eagle F1 SuperSport tires (“subject tires”) manufactured in Hanau, Germany during DOT week 3625 thru 3725 (September 07, 2025, to September 20, 2025), fail to conform with an internal conformity of production lab wheel test. Goodyear is therefore conducting a voluntary recall to replace the subject tires free of charge, including mounting and balancing. We are contacting you because records indicate that you may have purchased one or more of the subject tires.

What is the Problem?

Certain Goodyear Eagle F1 SuperSport tires, size **255/35ZR20 97Y**, from weeks 3625 to 3725 (9/7/2025 – 9/20/2025), fail to conform with an internal conformity of production lab wheel test indicating a potential tread separation condition. This tread separation condition could lead to loss of vehicle control, resulting in increased risk of a crash.

What Tires are Affected?

This recall involves the following tire:

Size	Type	Product Code	DOT Number
255/35ZR20 97Y	Goodyear Eagle F1 SuperSport	112-284-591	1DM5VJACR3625 to 3725

What Should You Do?

If you own one or more of the subject tires, the tire(s) will be replaced at no charge to you with another 255/35ZR20 Eagle F1 SuperSport from a different stock keeping unit, including mounting and balancing. We recommend that you contact a Goodyear retailer as described below when you receive this letter. To be eligible for a free replacement, you must return your tires to an authorized dealer on or before December 31, 2026. Please take this letter to the dealer at the

time of your appointment. The time required to determine if the tire is subject to recall is only a few minutes and approximately thirty (30) minutes per tire if replacement is required. The actual time at the dealership may vary depending on their workload. The tire identification number should not be removed until such time that the tire is destroyed or otherwise rendered permanently unusable, and Goodyear will instruct the tire dealer replacing the recalled tire to provide this service.

Reimbursement

If you have already replaced any of the tires covered by this recall, you may be eligible for reimbursement. Reimbursements are limited to warranty transactions where you paid a portion of the total price of a tire to replace an affected tire. Documentation that adequately supports eligibility must be provided for reimbursement. Submit a copy of your replacement tire invoice/receipt and if available a copy of the tire adjustment claim form to the following address for reimbursement:

The Goodyear Tire & Rubber Company
Attn: Dept. 728, Customer Assistance Center
200 Innovation Way
Akron, OH 44316-0001

Contact the Goodyear retailer where you purchased the tires or contact your nearest authorized Goodyear retailer. To find the nearest retailer, go to www.goodyear.ca and enter your location information in the Store Directory tab (under Support) or call 1-800-592-3267. The retailer will inspect the tires and let you know if they fall within the scope of this recall and therefore qualify for free replacement as part of this recall.

Questions?

If further assistance is required for any reason, including difficulty in obtaining free replacement tires, please contact Goodyear Consumer Relations, D728 at 200 Innovation Way, Akron, Ohio 44316, or by calling toll free 1-800-387-3288, option 1 for English, option 2 for French.

If after contacting your tire dealer or Goodyear Consumer Relations, you should have additional questions regarding this recall, you may contact the Motor Vehicle Safety Directorate, Transport Canada, 330 Sparks St., Ottawa, Ontario, K1A 0N5; or call the toll-free 1-800-333-0371; or email at mvs-sa@tc.gc.ca.

We apologize for any inconvenience this may cause you and thank you for your attention to this important matter. Your continued satisfaction is of the utmost importance to Goodyear Canada Inc.

Sincerely,

Goodyear Canada Inc.